

**Hilliard Tractor Club Formula for Computing Cubic inches;
.7854 X Bore X Bore X Stroke = Cubic Inches
Hilliard Tractor Club, Inc reserves the right to tech any tractor.**

**HILLIARD TRACTOR CLUB, INC. RESERVES THE RIGHT TO AMEND AND ADD RULES
AS NEEDED, TO PROMOTE SAFETY AND FAIRNESS.**

PRESIDENT: JOHN M. DONAVAN

VICE PRESIDENT: RON STOOLFIRE

SECRETARY: KELLY NICHOLS

TREASURER: CONNIE MORGENSTERN

TRUSTEES

RUSS NICHOLS

JIM MORGENSTERN

GARY STARK